


01807.001033.



*Cafe \$*  
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: )  
SYLVAIN JOYEAU et al. )  
Appl. No.: 09/882,301 )  
Filed: June 18, 2001 )  
For: DEVICE AND METHOD FOR )  
CONTROLLING ACCESS TO )  
COMPUTER PERIPHERALS )  
U.S. Patent No.: 6,898,643 B2 )  
Issued: May 24, 2005 )      October 11, 2005

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

*Certificate  
OCT 17 2005  
of Correction*

REQUEST FOR  
CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/13/2005 HLE333 0000068 6898643

01 FC:1811

100.00 0P

*OCT 18 2005*

Patentees' undersigned attorney may be reached in our Costa Mesa, CA office at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank L. Cire  
Attorney for Patentees  
Registration No. 42,419

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

CA\_MAIN 103185v1

OCT 18 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,898,643 B2

DATED : May 24, 2005

INVENTOR(S) : Joyeau et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 1:**

Line 16, "a" (first occurrence) should read -- an --.

**COLUMN 3:**

Line 16, "whilst" should read -- while --; and

Line 52, "on" should read -- and on --.

**COLUMN 4:**

Line 40, "of" should be deleted; and

Line 55, "an data bus 2" should read -- a data bus 2, --.

**COLUMN 5:**

Line 25, "peripherals" should read -- peripherals. --.

**COLUMN 6:**

Line 36, "tghe" should rad -- the --.

**COLUMN 12:**

Line 2, "read" should read -- read --.

CA\_MAIN 103171v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,898,643 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)  
(Form#30)

→ \_\_\_\_\_  
OCT 18 2005